

# MSP430F123 Device Erratasheet

## 1 Revision History

 $\checkmark$  The check mark indicates that the issue is present in the specified revision.

Errata Number	Rev A
BCL5	$\checkmark$
CPU4	$\checkmark$
EEM20	$\checkmark$
JTAG11	✓
PORT3	$\checkmark$
RES4	$\checkmark$
TA12	$\checkmark$
TA16	< <
TA21	<
TAB22	$\checkmark$
US13	$\checkmark$
US15	$\checkmark$
WDG2	$\checkmark$

1



Package Markings

www.ti.com

## 2 Package Markings

```
DW28
```

SOP (DW), 28 Pin

♥ YMLLLLS M430Fxxx NEV #	<ul> <li>YM = Year and Month Date Code</li> <li>LLLL = Assembly Lot Code</li> <li>S = Assembly Site Code</li> <li># = DIE Revision</li> <li>o = PIN 1</li> </ul>
♥ YMLLLLS M430Fxxx O G4REV #	<ul> <li>YM = Year and Month Date Code</li> <li>LLLL = Assembly Lot Code</li> <li>S = Assembly Site Code</li> <li># = DIE Revision</li> <li>o = PIN 1</li> </ul>

### **PW28**

TSSOP (PW), 28 Pin

4Fxxxxx YMS # O <sup>LLLL</sup>	YM = Year and Month Date Code LLLL = Assembly Lot Code S = Assembly Site Code # = DIE Revision o = PIN 1
MSP430Fxxxx YMS <u>G4</u> LLLL #	<ul> <li>YM = Year and Month Date Code</li> <li>LLLL = Assembly Lot Code</li> <li>S = Assembly Site Code</li> <li># = DIE Revision</li> <li>o = PIN 1</li> </ul>

### RHB32

QFN (RHB), 32 Pin

O MSP430 Fxxxx TI YMS# LLLL <u>G4</u>	1	<ul> <li>Year and Month Date Code</li> <li>Assembly Lot Code</li> <li>Assembly Site Code</li> <li>DIE Revision</li> <li>PIN 1</li> </ul>
--	---	--



#### www.ti.com

3 Detailed Bug Description			
BCL5	BCS Module		
Function	RSELx bit modifications can generate high frequency spikes on MCLK		
Description	When $DIVMx = 00$ or 01 the RSELx bits of the Basic Clock Module are incremented or decremented in steps of 2 or greater, the DCO output may momentarily generate high frequency spikes on MCLK, which may corrupt CPU operation. This is not an issue when $DIVMx = 10$ or 11.		
Workaround	Set DIVMx = 10 or 11 to divide the MCLK input prior to modifying RSELx. After the RSELx bits are configured as desired, the DIVMx setting can be changed back to the original selection.		
CPU4	CPU Module		
Function	PUSH #4, PUSH #8CPU4 - Bug		
Description	The single operand instruction PUSH cannot use the internal constants (CG) 4 and 8. The other internal constants (0, 1, 2, -1) can be used. The number of clock cycles is different:		
	PUSH #CG uses address mode 00, requiring 3 cycles, 1 word instruction		
	PUSH #4/#8 uses address mode 11, requiring 5 cycles, 2 word instruction		

Workaround Refer to the table below for compiler-specific fix implementation information.

IDE/Compiler	Version Number	Notes
IAR Embedded Workbench	IAR EW430 v2.x until v6.20	User is required to add the compiler flag option below. hw_workaround=CPU4
IAR Embedded Workbench	IAR EW430 v6.20 or later	Workaround is automatically enabled
TI MSP430 Compiler Tools (Code Composer Studio)	v1.1 or later	
MSP430 GNU Compiler (MSP430-GCC)	MSP430-GCC 4.9 build 167 or later	

EEM20	EEM Module		
Function	Debugger might clear interrupt flags		
Description	During debugging read-sensitive interrupt flags might be cleared as soon as the debugger stops. This is valid in both single-stepping and free run modes.		
Workaround	None.		
JTAG11	JTAG Module		
Function	Debug with JTAG interface		
Description	The debug operation using the JTAG interface of a program executed in the RAM is not possible. The RAM content gets corrupted.		



Detailed Bug Descript	tion www.ti.com
Workaround	None
PORT3	PORT Module
Function	Port interrupts can get lost
Description	Port interrupts can get lost if they occur during CPU
	access of the P1IFG and P2IFG registers.
Workaround	None
RES4	RESET Module
Function	No reset if external resistor exceeds certain value
Description	No reset of the device is performed if the external pull down resistor on RST/NMI pin is above a certain limit. The limits are:
	Vcc = 1.8V: maximum pull down resistor = 12 kohm
	Vcc = 3.0V: maximum pull down resistor = 5 kohm
	Vcc = 3.6V: maximum pull down resistor = 2.5 kohm
	In addition, a higher current consumption occurs during high/low RST/NMI signal transition when using improper resistors.
Workaround	Use external pulldown resistors below the listed values or directly drive RST/NMI low to generate a reset.
TA12	TIMER_A Module
Function	Interrupt is lost (slow ACLK)
Description	Timer_A counter is running with slow clock (external TACLK or ACLK)compared to MCLK. The compare mode is selected for the capture/compare channel and the CCRx register is incremented by one with the occurring compare interrupt (if TAR = CCRx). Due to the fast MCLK the CCRx register increment (CCRx = CCRx+1) happens before the Timer_A counter has incremented again. Therefore the next compare interrupt should happen at once with the next Timer_A counter increment (if TAR = CCRx + 1). This interrupt gets lost.
Workaround	Switch capture/compare mode to capture mode before the CCRx register increment. Switch back to compare mode afterwards.
TA16	TIMER_A Module
Function	First increment of TAR erroneous when $IDx > 00$
Description	The first increment of TAR after any timer clear event (POR/TACLR) happens immediately following the first positive edge of the selected clock source (INCLK, SMCLK, ACLK or TACLK). This is independent of the clock input divider settings (ID0, ID1). All following TAR increments are performed correctly with the selected IDx settings.
Workaround	None

4



# TA21


www.ti.com

### TIMER\_A Module

Function TAIFG Flag is erroneously set after Timer A restarts in Up Mode

Description

In Up Mode, the TAIFG flag should only be set when the timer counts from TACCR0 to zero. However, if the Timer A is stopped at TAR = TACCR0, then cleared (TAR=0) by setting the TACLR bit, and finally restarted in Up Mode, the next rising edge of the TACLK will erroneously set the TAIFG flag.



Workaround None.

TAB22	TIMER_A/TIMER_B Module			
Function	Timer_A/Timer_B register modification after Watchdog Timer PUC			
Description	Unwanted modification of the Timer_A/Timer_B registers TACTL/TBCTL and TAIV/TBIV can occur when a PUC is generated by the Watchdog Timer(WDT) in Watchdog mode and any Timer_A/Timer_B counter register TACCRx/TBCCRx is incremented/decremented (Timer_A/Timer_B does not need to be running).			
Workaround	Initialize TACTL/TBCTL register after the reset occurs using a MOV instruction (BIS/BIC may not fully initialize the register). TAIV/TBIV is automatically cleared following this initialization.			
	Example code:			
	MOV.W #VAL, &TACTL			
	or			
	MOV.W #VAL, &TBCTL			
	Where, VAL=0, if Timer is not used in application otherwise, user defined per desired function.			
US13	USART Module			
Function	Unpredictable program execution			
Description	USART interrupts requested by URXS can result in unpredictable program execution if this request is not served within two bit times of the received data.			
Workaround	Ensure that the interrupt service routine is entered within two bit times of the received data.			



www.ti.com

Detailed Bug Description

US15	USART Module
Function	UART receive with two stop bits
Description	USART hardware does not detect a missing second stop bit when SPB = 1.
	The Framing Error Flag (FE) will not be set under this condition and erroneous data reception may occur.
Workaround	None (Configure USART for a single stop bit, $SPB = 0$ )
WDG2	WDT Module
Function	Incorrectly accessing a flash control register
Description	If a key violation is caused by incorrectly accessing a flash control register, the watchdog interrupt flag is set in addition to the expected PUC.
Workaround	None



#### www.ti.com

### 4 Document Revision History

Changes from family erratasheet to device specific erratasheet.

- 1. Errata TA22 was renamed to TAB22
- 2. Description for TAB22 was updated

Changes from device specific erratasheet to document Revision A.

1. Errata EEM20 was added to the errata documentation.

Changes from document Revision A to Revision B.

1. Errata TA21 was added to the errata documentation.

Changes from document Revision B to Revision C.

1. Package Markings section was updated.

Changes from document Revision C to Revision D.

1. TA21 Description was updated.

Changes from document Revision D to Revision E.

- 1. Function for CPU4 was updated.
- 2. Workaround for CPU4 was updated.

### **IMPORTANT NOTICE**

Texas Instruments Incorporated and its subsidiaries (TI) reserve the right to make corrections, enhancements, improvements and other changes to its semiconductor products and services per JESD46, latest issue, and to discontinue any product or service per JESD48, latest issue. Buyers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. All semiconductor products (also referred to herein as "components") are sold subject to TI's terms and conditions of sale supplied at the time of order acknowledgment.

TI warrants performance of its components to the specifications applicable at the time of sale, in accordance with the warranty in TI's terms and conditions of sale of semiconductor products. Testing and other quality control techniques are used to the extent TI deems necessary to support this warranty. Except where mandated by applicable law, testing of all parameters of each component is not necessarily performed.

TI assumes no liability for applications assistance or the design of Buyers' products. Buyers are responsible for their products and applications using TI components. To minimize the risks associated with Buyers' products and applications, Buyers should provide adequate design and operating safeguards.

TI does not warrant or represent that any license, either express or implied, is granted under any patent right, copyright, mask work right, or other intellectual property right relating to any combination, machine, or process in which TI components or services are used. Information published by TI regarding third-party products or services does not constitute a license to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

Reproduction of significant portions of TI information in TI data books or data sheets is permissible only if reproduction is without alteration and is accompanied by all associated warranties, conditions, limitations, and notices. TI is not responsible or liable for such altered documentation. Information of third parties may be subject to additional restrictions.

Resale of TI components or services with statements different from or beyond the parameters stated by TI for that component or service voids all express and any implied warranties for the associated TI component or service and is an unfair and deceptive business practice. TI is not responsible or liable for any such statements.

Buyer acknowledges and agrees that it is solely responsible for compliance with all legal, regulatory and safety-related requirements concerning its products, and any use of TI components in its applications, notwithstanding any applications-related information or support that may be provided by TI. Buyer represents and agrees that it has all the necessary expertise to create and implement safeguards which anticipate dangerous consequences of failures, monitor failures and their consequences, lessen the likelihood of failures that might cause harm and take appropriate remedial actions. Buyer will fully indemnify TI and its representatives against any damages arising out of the use of any TI components in safety-critical applications.

In some cases, TI components may be promoted specifically to facilitate safety-related applications. With such components, TI's goal is to help enable customers to design and create their own end-product solutions that meet applicable functional safety standards and requirements. Nonetheless, such components are subject to these terms.

No TI components are authorized for use in FDA Class III (or similar life-critical medical equipment) unless authorized officers of the parties have executed a special agreement specifically governing such use.

Only those TI components which TI has specifically designated as military grade or "enhanced plastic" are designed and intended for use in military/aerospace applications or environments. Buyer acknowledges and agrees that any military or aerospace use of TI components which have *not* been so designated is solely at the Buyer's risk, and that Buyer is solely responsible for compliance with all legal and regulatory requirements in connection with such use.

TI has specifically designated certain components as meeting ISO/TS16949 requirements, mainly for automotive use. In any case of use of non-designated products, TI will not be responsible for any failure to meet ISO/TS16949.

Products Audio Amplifiers Data Converters DLP® Products	www.ti.com/audio amplifier.ti.com dataconverter.ti.com www.dlp.com	Applications Automotive and Transportation Communications and Telecom Computers and Peripherals Consumer Electronics	www.ti.com/automotive www.ti.com/communications www.ti.com/computers www.ti.com/consumer-apps
DSP	dsp.ti.com	Energy and Lighting	www.ti.com/energy
Clocks and Timers	www.ti.com/clocks	Industrial	www.ti.com/industrial
Interface	interface.ti.com	Medical	www.ti.com/medical
Logic	logic.ti.com	Security	www.ti.com/security
Power Mgmt	power.ti.com	Space, Avionics and Defense	www.ti.com/space-avionics-defense
Microcontrollers	microcontroller.ti.com	Video and Imaging	www.ti.com/video
RFID	www.ti-rfid.com		
OMAP Applications Processors	www.ti.com/omap	TI E2E Community	e2e.ti.com
Wireless Connectivity	www.ti.com/wirelessconne	ctivity	

Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265 Copyright © 2016, Texas Instruments Incorporated